

Offloading a Sign from the Delivery Truck

The following is one option you can use when offloading your sign from the delivery truck. If you feel more comfortable with another method, please utilize the option that best fits your unique situation.*

Be sure you know how much your sign weighs before organizing help for the delivery. Your sign consultant can give you the approximate weight of the crated sign weeks before it ships. As a general rule you should have one able person for every one hundred pounds. You will typically need a minimum of four people to offload the sign.

STEP 1



STEP 2



STEP 3



When offloading the sign, it is generally easiest when the sign is brought to the edge of the truck, tilted, and slid down as illustrated above. This typically results in never having to lift the entire weight.

If your sign weighs 600 pounds or more or you are not 100% confident that you have enough manpower, we recommend lifting equipment. **ALWAYS THINK SAFETY FIRST.**

In addition, if the delivery truck cannot park near the installation site, removing the crate reduces the weight by 100-150 pounds.

**Please note that this document is meant as a guideline and the delivery process is the full responsibility of the customer. J.M. Stewart Corporation and its employees are to be held harmless from the individual decisions and actions involved in the process.*